

CERTIFIED LAND CORNER RESTORATION

Index No. A-23

T 31 N R 13 E

State of Wisconsin }
County of Lan glade } ss.

I Raymond J. Hallisy, do hereby certify that on the 31st day of March, 1985, I found evidence of the 1/4 corner of 1 & 36 Township 32 & 31, North, Range 13 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....


History of original corner establishment:

Corner Established in 1900 By
County surveyor

Description of corner evidence found:

4 inch Brass cap set in cement post, Rock mound
corner pulled out by logging, Road construction
old B.T.s

20" Hard maple OK.
16" Hard maple OK.




Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.s Reset corner by B.T.s

12" Twin Hard maple N34E 10.7 FT
10" Hard maple S46°E 34.8 FT.
20" Hard maple OK.
16" Hard maple OK.

New Rock mound
AROUND CORNER

T 31 N R 13 E



○ = Corner monument restored.

Dated at Antigo, Wis., this 31st day of March, 1985.

Signature Raymond J. Hallisy Title land surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy

