

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin } ss.
County of Langlade }

I Milo E. Stefan, do hereby certify that on the 16th day of November, 1982, I found evidence of the West Quarter corner of Section 4 Township 32N, Range 14E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:


Surveyed in 1857 by Alfred Millard 41.26 chains, set wood post Lynn, 12", N9°E, 15 lks. Lynn, 16", S3°W, 4 lks.

Description of corner evidence found:


Large stump hole, N9°E, 9.9' Local Evidence: Found 4" x 4" x 5' Cedar post with corner location poster on south side in mound of rock - 1 1/4" iron pipe alongside. Corner is 40.00 chains north of post set for section corner - 4, 5, 8, and 9. East-west cutting line extends east-north-south. Cutting line extends north.

Description of monument and accessories I established to perpetuate the location of this corner:

Placed a 2" x 36" aluminum monument in mound of stone with tablet stamped as follows: T32N, R14E, 1/4, S5, S4, 1982, RLS-1558 From which the following bear: Sugar, 10", N14°E, 35.15' Hickory, 8", S81°E, 21.67' Sugar, 5", S57°W, 10.77' Sugar, 6", N42°W, 42.78' Steel Sign Post, South, 2.00'



● - Corner monument restored
□ -



Resident witnesses.....

Dated at Rhinelander Wisconsin, this 2 day of May 19 82.....

Signature Milo E. Stefan Title Land Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)
Surveyors Registration No. RLS-1558.....

Office of County of
I hereby certify that the within instrument was filed in this office for record on the day of 19....., and was filed in Book No. Page No. of County Records.

Signature Title

C-9