

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

3214250000

Index No. V-1 V25
3214

State of Wisconsin }
County of Oconto } ss.

I, John C. Schulke, do hereby certify that on the 5th day of August, 1987, I found evidence of the Southwest corner of ~~XXXXXXXXXX~~ Section 30 Township thirty-two, North, Range 15 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

History of original corner establishment:

The original corner established in 1857 by Artemas Curtis. Set a wooden post with the following GLO corner references:

Yellow Birch	14"	S47°W	53 lks.
Beech	10"	N65°W	20 lks.
Tamarack	10"	S68°E	42 lks.
Hemlock	12"	N54°E	64 lks.
Pond		South	0.58 chains
Pond		East	0.75 chains

Description of corner evidence found:

Recovered a 2 1/2" dia. galvanized iron pipe with a brass tablet stamped to identify the corner set by J. F. Resvick in 1969. Monument in place and an old square wood post is 1.6 feet Northwest.


Recovered the following bearing trees:

Maple	15"	N67°W	26.51 feet
Yel. Birch	15"	S39°W	31.62 feet
Dieing Red Maple	9"	N37°E	47.62 feet

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed, scribed and painted the following new bearing trees:

Red Maple	13"	N11°E	31.73 feet
Red Maple clump	10"	S13°E	21.24 feet



○ = Corner monument restored.

Dated at Hiles, Wis., this 2nd day of November, 1987


Signature: *John C. Schulke* Title: Land Surveyor Registration No. S-1665
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM NO. 985-A



Stock No. 26273


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Found perpetuated location.

(g)(h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?
No.



John Schulke

(i) I, John C. Schulke certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

John C. Schulke Nov 2nd 1987
Signature Date

