	T:31N :	RI4E	
	, , , , , , , , , , , , , , , , , , ,]	ı
	[1
	!		
			1
	_ Sect	<u> </u>	!
	. 1		1
	1		1
			 !
1	! !	1	!
1	i	1	1

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION


Index No. **12-23**

History of original corner establishment:

ORIGINAL CORNER ESTABLISHED BY ARTEMAS CURTIS, DEP. SURVEYOR, IN 1857.

Description of corner evidence found:

REPLACED IRON BED RAIL OF LYKNOWN ORIGIN WHICH AGREES WITHIN REASON OF PROPORTIONED LOCATION OF CORNER. SET 2" & 3L" ALUMINUM MONUMENT. Work Done By John Fisher In Oct. 1923



Description of monument and accessories I established to perpetuate the original locative of this corner.

ar ar monument and accessor	les I established to perpetuate the original location of
a.	TRED PINE 7- RED PINE 1-136. ALUMINUM PIPE WITH THE STEEL POST TO IDENTIFY CORNER STEEL POST NISHN

Dated at <u>Eccho</u>	, Wis	, this 14 ±	day of	MARCH	. 19 83
Signature Wellem (County	on Kelly Surveyor, Registered Land	Title <u>Coun</u> 1 Surveyor, or oth	77 SURYE 40 cr duly authorized of	Registrati	on No <i>1098</i>
Office of Register of Deed nstrument was filed in the turn o'clock	ds, County ofhis office for record on			7 1 1	
	(Register of Deeds)		•		