

CERTIFIED LAND CORNER RESTORATION

33-9

Index No. D-1

State of Wisconsin } ss.  
County of Langlade }

History of original corner establishment:

Corner set in the 1930's

I, Raymond J. Hallisy, do hereby certify that on the 20th day of July, 1968, I found evidence of the S 1/16 corner of Section 6 Township 33, North, Range 9, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found wood stake standing, 2" iron pipe on E side  
Marked W 50 LKS to Cor. S1/16 S1 S6



Resident witnesses:

.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set Std. pipe with cap marked W. C. 50 LKS W to Cor. S1/16 S1 S6

FORM 985 H. C. MILLER CO., MILWAUKEE



Dated at Antigo, Wis., this 20th day of July, 1968.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy

○ = Corner monument restored.