

CERTIFIED LAND CORNER RESTORATION

33-9

Index No. H-1

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy do hereby certify that on the 16 day of November, 1969, I found evidence of the S 1/16 corner of Section 7 Township 33, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:


Found old stake leaning, marked s/16 S 7 Cor 50 LKS W.

Resident witnesses:


.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.  
B.T.'s to witness corner.  
8" White Spruce N31E 6 Ft. 7 inches.  
11" Red Maple S44E 10 Ft. 11 inches.  
B.T.'s faced at base of tree and scribed BT.



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 16th day of November, 1969

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By \_\_\_\_\_ Deputy