
Cou	nty of	LANGLA	OE		ss.
certi of evid corn Tow as de I est	ence of the ence o	on the EPTEMBI the 33 E Fhereon; and a new many hereon to hereon to hereon.	25 sourth Plad that foonumen	, 19.7.7, No rincipal rom thint and	, I fo , I fo , Merid s evide accesso
Resi	dent wit	nesses:			
*****				• • • • • • • • • • • • • • • • • • • •	
		T. 33N.	<u>- R.9</u>	E	
	1		1	 	
	**]	1	
	- T	Mariel Males records Process		- T	
3	1	de cong		1	
» ф -		5	10	- + -	
ž I			1		
2			1	1	
COUNTY LINE	1 1 - 1		1]] !	
	<u>!</u> !] 	
	! !		 	 	

State of Wisconsin

CERTIFIED	LAND	CORNER	RESTORAT	ION

History of original corner establishment:



Description of corner evidence found:

CORNER PROPORTIONED FROM ORIGINAL NOTES BETWEEN NW CORNER AND SW CORNER SECTION 30 T.33N.-R.9E.

LOCATED SECTION CORNER STONES SET IN THE 1920'S.

Description of monument and accessories I established to perpetuate the original location of this corner.

	1		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	5" BALSI	94	
(6" BALSAM	10606 - 50.50		
1 X 586° W	NEW Y-Y-Y-Y-DED F	ENCE RUNNING E-W	CECT
N 6 58.70		733N , T33N	July Sol
1	SET 14 CORNE	RE REE	1 133N C
566.60	2" x 42" IRON	PIPE WITH BRASS CAP	25 4 30
1000	9 IN ROAD.	MARKED:	7 R8E R9E
-7" ASPEN E	BLAZE TREES	MARKED: (2)	1.036
(%)			9-16-77
3	((1)	WEK
Dated at	ELCHO, Wis., this	1674 day of SE	PTEMBER , 1977
22	0.0	•	
Signature William +. Re	Lley Title RE61STE	RED LAND SURVEYOR	Registration No. 5.1098
	or, Registered Land Surveyor, or o	·	
Office of Register of Deeds, Co	unty of	, I h	ereby certify that the withir
instrument was filed in this offi		day of	, 19
ato'clock	M.		
(Regist	ter of Deeds)	•	
(Regist	ici di Becco,		
***	ā		