## U. S. PUBLIC LAND SURVEY MONUMENT RECORD


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.


BY J.M. MARSH IN JULY AUGUST 1851



T 33N R9E

(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

LOCATED 646 MARSLE MCHUMENT 12" BELOW POADSURFACE, MONIMED BEEN DISTURBED BY GRADER, SET 1" IRON PIPE AS COPNER LOCATION, MARRED WITHESS MCHUMENTS. DISTURBED STONE MON. LEFT INPLACE.



| (e) | Describe any material discrepancy between the location of the corner as restored or   |
|-----|---|
|     | reestablished and the location of that corner as previously restored or reestablished |
|     | by distance and direction. Show the discrepancy on the plan view drawing under (d),   |
|     | above. Show the distances between the corner as previously restored or reestablished  |
|     | and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness |
|     | monuments shown on the drawing in (d), above.   |

NONE

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(24)

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

NO

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

