

CERTIFIED LAND CORNER RESTORATION

33-9  
Index No. E-20

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930's

I Raymond J. Hallisy, do hereby certify that on the 10th day of June, 1968, I found evidence of the E 1/16 corner of Section 11 Township 33, North, Range 9, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found squared stake standing, top poor, bottom good.  
Marked E 1/16 S11 S2 30 lks S.

Resident witnesses:

.....  
.....  
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set Std. 1 1/2" ~~XX~~ pipe with cap marked W.C. C. 30 LKS. S. E 1/16  
BT's to witness corner

11" TAMARACK  
SCRIBED BT → ○  
N62W 55'8"

○ 10" TAMARACK SCRIBED BT  
R N64E 41'8"

IP → ● STONE RD



○ = Corner monument restored.

Dated at Antigo, Wis., this 10th day of June, 1968.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 1685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

.....  
(Register of Deeds)

By..... Deputy