

CERTIFIED LAND CORNER RESTORATION

33-9
Index No. E-15

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I, Raymond J. Hallisy, do hereby certify that on the 10th day of May, 1970, I found evidence of the W 1/16 corner of Section 2 Township 33, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

~~XXXXXXXX~~

Found old stake standing in fence on north side of Hwy. "T"
Marked S2 S11 W1/16 Cor 10 lks S


Resident witnesses:

J. Weir
J. Krupke

Description of monument and accessories I established to perpetuate the original location of this corner

Set 2" pipe with brass cap, rock mound.
No B.T.'s

FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.



Dated at Antigo, Wis., this 10th day of May, 1970

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy