State	of	Wisconsin		
			SS.	

County of Langlade

Glen Barker do hereby certify that on the ____dth ____day CHARLES SW. 1/16 corner of Section 4 Township......33...., North, Range9. East......, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accession as described hereon to perpetuate the original accession.

Resident witnesses:

J. Claflin - R

H. Wagoner

NO SURVE

BARKER

S-1682 CRANDON

T33N R9E

O = Corner monument restored.

History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

Corner established by subdivision of the SW 1/4. SW 1/16 sets 1340.87 ft. of W.C. 1/16 and 1334.77 ft. of SC 1/16.

Description of monument and accessories I established to perpetuate the original location of this corner. Set a 2" iron pipe with brass cap stamped: T33N R9E Monument projects 18" above ground. S 4 Marked NBTs: SW 1/16 Cherry 5" 16.71 ft. Maple 10" N33W 16.05 ft. S1682 - 1983 Scribed 1/16 - B.T.

Rhinelander Dated at	Wis this 9th	day of	June	19.83
Dated at Rhinelander Signature Our County Surveyor, Regist	Title Registered	Land Surveyor	Registratio	n No.S1682
Office of Register of Deeds, County of instrument was filed in this office for reat				
(Register of Dee	ds)	.		