

CERTIFIED LAND CORNER RESTORATION

Index No. E-8

State of Wisconsin }  
County of Lanlade } ss.

I Daniel K. Pleoger, do hereby  
certify that on the 30 day  
of December, 19 80, I found  
evidence of the E 1/16  
Est. ~~corner~~ corner of Sections 5 & 8  
Township 33, North, Range  
9 east, Fourth Principal Meridian,  
as described hereon; and that from this evidence  
I established a new monument and accessories  
as described hereon to perpetuate the original  
location of this corner.


History of original corner establishment:

No evidence of any previous corner

Description of corner evidence found:

Total distance from section corner 4-5-8-9 to 1/4 corner between Section 5 & 8 is  
2658.25 ft. at bearing N88-22-14W.  
Set E 1/16 1329.125 ft. intermediate.

Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.

Set a railroad spike in CTH "H" for true corner.  
Set a 1 1/2" iron pipe with screw on brass cap south 55.65 ft of true corner for  
witness corner stamped:

Monument projects 12" above ground

Marked NBTs to true corner


Black ash 6" S36W 78.00 ft.

Twin maple 8" S46E 82.38 ft.

Scribed 1/16 B.T.

T33N R9E  
E 1/16  $\frac{S}{8} \frac{5}{8}$  W.C.  
N55.65 ft.  
S1537 - 1980

FORM 985 K. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 22 day of September, 19 81

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within  
instrument was filed in this office for record on the..... day of....., 19.....  
at..... o'clock..... M.

(Register of Deeds)

By..... Deputy