

CERTIFIED LAND CORNER RESTORATION

Index No. E-7


State of Wisconsin } ss.  
County of Langlade

I Daniel K. Pleoger, do hereby certify that on the 29 day of December, 19 80, I found evidence of the Quarter corner of Sections 5 & 8 Township 33 North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Original corner established by H.C. Fellows Gov. Deputy Surveyor in 1859 from which hemlock 12" bears N32W 8 lks and hemlock 11" bears S61W 17 lks.

Description of corner evidence found:

Total distance from section corner 5-6-7-8 to section corner 4-5-8-9 is 5316.50 ft. at bearing S88-22-14E.  
Set 1/4 corner 2658.25 ft. intermediate

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a railroad spike in CTH "H" for true corner  
Set a 2 1/2" iron pipe with screw on brass cap S30W 56.38 ft of true corner  
for witness corner stamped:

Monument projects 18" above ground  
Marked NBTs to true corner  
Black ash 6" S51E 81.40 ft.  
Cedar 6" S29W 83.50 ft.

Scribed 1/4 - B.T.

T33N R9E  
1/4 S 5/8 W.C.  
N30W - 56.38 ft.  
S1537 - 1980

Dated at Rhinelander, Wis., this 22 day of September, 19 81

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy