

CERTIFIED LAND CORNER RESTORATION

33-9

Index No. D-9

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy do hereby certify that on the 2nd day of May, 19 70, I found evidence of the S 1/16 corner of Section 4 Township T33, North, Range R9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Corner set in the 1930 resurvey.


Description of corner evidence found:
Found old stake down, point in ground, marks not plain.

Resident witnesses:
J. Weir
J. Krupka

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.
New B.T.'s
Yellow Birch 18" S73E 21 Ft. 4 inches.
Yellow Birch 14" S46W 15 Ft. 9 inches.
B.T.'s faced at base of tree and scribed BT.

FORM 985 M. C. MILLER CO., MILWAUKEE



Dated at Antigo, Wis., this 2nd day of May, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.