

CERTIFIED LAND CORNER RESTORATION

Index No. D-6

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:


No evidence of any previous corner.

I Daniel K. Plegger, do hereby certify that on the 21st day of January, 1981, I ~~found~~ ^{established} ~~evidence of the~~ ^{SW 1/16} corner of section 5 Township 33, North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Corner established by subdivision of SW 1/4.
Location of SW 1/16 corner is N 88-15-28 W 1318.729 feet of SC 1/16 and S 4-01-03 W 1349.931 feet of W.C. 1/16.

Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.


Set a 1-1/2" iron pipe with brass cap - stamped:
Monument projects 18" above ground.

Marked NBT's:

Black Spruce 14" S24°W 52.0 feet
Black Ash 7" S58°E 46.02 feet
both scribed 1/16 B.T.

T33N R9E
SW 1/16 S⁺5

S1537-1981



○ = Corner monument restored.

Dated at Rhineland, Wis., this 27th day of April, 1981.

Signature Daniel K. Plegger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 965 H. C. MILLER CO., MILWAUKEE