


CERTIFIED LAND CORNER RESTORATION

Index No. C-9


State of Wisconsin } ss.  
County of Langlade }

I Daniel K. Pleoger, do hereby certify that on the 31st day of December, 19.80, I found evidence of the Quarter corner of Sections 4 and 5 Township 33, North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



FORM 985 K C MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Original corner established by H.C. Fellows, deputy surveyor, in 1859 from which Cedar 15" bears N27°W 40 links and Spruce 12" bears S21°W 6 links.

Description of corner evidence found:

Recovered a 4" iron pipe filled with concrete and capped with a 4" diameter brass cap - stamped:  
Monument projects 12" above ground.  
O.B.T. original Cedar 15" N27°W 40.0 links, stump remains - badly rotted.

Langlade County  
T33N R9E  
1/4S 5 4  
4-13-38

Description of monument and accessories I established to perpetuate the original location of this corner.

Monument left as recovered.  
Marked NBT's:  
Maple 8" N13°W 22.38 feet  
Maple 6" S15°W 48.40 feet  
Cedar 12" S41°E 33.63 feet  
scribed 1/4 - BT

Dated at Rhinelander, Wis., this 23rd day of March, 19 81

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy