	31	S-1	
	0,	4	RVE TOUR
	•	80 D	EN
		37.75 C	A CORPOR
	T33N	R9E	90.00
1 :		! 1	1
!		' 	i 1
i		, 	1
		'	!
!		1	<u> </u>
1		!]	<u> </u>
1	s	' 5	
	(b	<u> </u>
 	`	r	1
ì		C 1/4	1
i		'	i L
		'	<u> </u>
			¦
i		1	<u> </u>
		· 	i
			1

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. C-7

History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

Corner established by traverse and computation.

Corner sets S 3-34-49 W 2837.432 feet of N 1/4 corner.

N 88-08-35 W 2651.49 feet of E 1/4 corner.

N 3-34-49 E 2693.902 feet of S 1/4 corner.

S 88-08-35 E 2616.697 feet of W 1/4 corner.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap - stamped: Monument projects 12" above ground.

Marked NBT's:

White Spruce 5" N56°W 24.65 feet T33N R9E

Maple 7" S63°W 56.09 feet S + 5

Maple 5" S23°E 60.05 feet C 1/4 + 5

scribed 1/16 B.T. S1537-1981

Dated at	Rhinelander	, Wis., this	24th	day of	April	, 19.81
	County Surveyor, Register					
Office of Reinstrument	egister of Deeds, County of was filed in this office for reco'clock				, I h	ereby certify that the within
	(Register of Deeds)		-		
_			_			