


CERTIFIED LAND CORNER RESTORATION

Index No. E-3


State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 18th day of December, 1980, I found evidence of the Quarter corner of Sections 6 and 7 Township 33, North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Original corner established by H.C. Fellows, deputy surveyor, in 1859 from which Tamarack 6" bears N27°W 13 links and Birch 14" bears S60°E 11 links.

Description of corner evidence found:

Recovered a 4" squared cedar post.
Recovered a B.T. tamarack 14" S25°E 14.80 feet - scribed 1/4S B.T.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced post with a 2-1/2" iron pipe with screw-on brass cap - stamped: Projecting 18" above ground.

Marked N.B.T.'s:

Cedar 12" S8°E 11.80 feet
Black Ash 5" N78°W 10.93 feet
Black Ash 7" N52°E 11.72 feet
all scribed 1/4 - B.T.

T33N R9E
1/4 S 6
S 7
S1537 - 1980

Dated at Rhineland, Wis., this 23rd day of March, 1981

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy