

CERTIFIED LAND CORNER RESTORATION

Index No. D-5

State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 30th day of December, 1980, I ~~found~~ established ~~corner~~ of the S 1/16 corner of Sections 5 and 6 Township 33, North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

From section corner 5,6,7,8 to 1/4 corner between sections 5 and 6 a distance of 2706.007 feet at bearing N 4-27-09 E.
Set S 1/16 corner 1353.004 feet intermediate.

Resident witnesses:




Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1/2" x 8" iron spike in old road bed of C.T.H. "H" for true corner.
Set a 1-1/2" I.D. iron pipe with screw-on brass cap 35.00 feet west of true corner for witness corner - cap stamped:
Monument projects 18" above ground.
Marked NBT to true corner.

Yellow Birch 10" N27°W 81.90 feet - scribed 1/16 B.T. T33N R9E
S 1/16 6 1/5 W.C.
E. 35 ft. to cor.
S1537-1980

FORM 983 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 24th day of April, 1981

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy