

CERTIFIED LAND CORNER RESTORATION

Index No. C-3

State of Wisconsin }
County of Langlade } ss.

I, Daniel K. Pledger, do hereby certify that on the 31st day of December, 1980, I ~~found~~ ^{established} evidence of the C 1/4 corner of Section 6 Township 33, North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

Corner established by traverse and computation.
Corner sets S3-05-53E 2750.23 feet of N 1/4 corner.
S88-06-02W 2714.60 feet of E 1/4 corner.
N3-05-53E 2679.335 feet of S 1/4 corner.
N88-06-02E 2951.934 feet of W 1/4 corner.

Resident witnesses:




Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap - stamped:
Monument projects 12" above ground.

Marked NBT's -
Maple 7" S10°E 28.77 feet
Maple 5" S38°E 46.40 feet
Wh. Spruce 12" N65°E 26.05 feet
scribed 1/4 B.T.

T33N R9E
S + 6
C 1/4
S1537

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 8th day of April, 1981.

Signature Daniel K. Pledger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy