O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. \overline{J} -5

History of original corner establishment:

DRIGINAL CORNER ESTABLISHED BY HIRAM C. FELLOWS IN SEPT. - OCT. , 1860.

Description of corner evidence found:

FOUND IN PLACE: 4" BRASS CAP
MONUMENT. MARKED 3 BT'S.
MON. EST. BY CCC IN 1938

(Register of Deeds)



William J. Hell

Description of monument and accessories I established to perpetuate the original location of this corner.

Λ	ALL BT'S NEW		€ 5F	e uc e	18 6 4 04	IBLADE COUNT	
NORTH	PK PK N	NAIL SET "X"	Na. N. N. S.	F BRASS CAP)	7_	R96	
Dated at	ELCHO.	Wis this	√310"5PR 7#	uc€ day of	DECEMBER	19.82	
	William J. Held (County Surveyor, Reg	Тitle	COUNTY	SURVEYO	Registrati	·	
instrument v	gister of Deeds, County of was filed in this office for 'clock						