

CERTIFIED LAND CORNER RESTORATION

33-9

Index No. F-17

State of Wisconsin }  
County of LANGLADE } ss.


I, RAYMOND J. HALLISY, do hereby certify that on the 24 day of MAY, 1969, I found evidence of the N 1/4 - WITNESS CORNER corner of SEC. 10 Township 33, North, Range 9 EAST, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

JERRY KRYKA

GERALD WEIX

FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

CORNER REESTABLISHED DURING 1930's, BY COUNTY RESURVEY PROJECT

Description of corner evidence found:

4" SQUARED POST MARKED " W.C. - 10 1/16 11 - CORNER 20 LKS E. "


Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2" IRON PIPE WITH BRASS CAP AND ROCK MOUND. MARKED

T33N R9E  
W.C. N 1/4  
S10 | S11  
COR. 20 LKS. E.

BEARING TREES (B.T.s) X = B.T.

- 1.) FENCE POST 2' 7" WEST
- 2.) ELK 16" N25°E 156'
- 3.) WHITE PINE 10" N80°E 136' 6"



Dated at ANTIGO, Wis., this 10<sup>th</sup> day of JUNE, 1969.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy