

CERTIFIED LAND CORNER RESTORATION

Index No. G-25

State of Wisconsin }
County of LANGHADE } ss.

I, RAYMOND J. HALLISY, do hereby certify that on the 2 day of AUGUST, 1980, I found evidence of the EAST 1/4 corner of SEC 12 Township T33N, North, Range 9E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


S. BARGANDER
L. BOUBANNAIS

History of original corner establishment:

1937-38 Re-Survey Project
OF T 33N R 9E BY D.A. HINTZ

Description of corner evidence found:

4" BRASS CAP IN IRON PIPE
AND CONCRETE
STONE MOUND
NO BEARING TREES




Description of monument and accessories I established to perpetuate the original location of this corner.

MARKED AND SCRIBED 4 BEARING TREES
ASPEN - 7" N26°E 34.9 FEET
RED (SOFT) MAPLE 10" S75°E 23.3 FEET
RED (SOFT) MAPLE 9" S42°W 7.7 FEET
HARD (SUGAR MAPLE 5" N32°W 8.2 FEET

FORM 985 M. C. MILLER CO. MILWAUKEE

T 33 N R 9 E



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 16 day of AUGUST, 1980.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy