

CERTIFIED LAND CORNER RESTORATION

Index No. N.23

State of Wisconsin }
County of Laneshade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy, do hereby certify that on the 7th day of April, 1979, I found evidence of the 1/4 corner of Section 13 & 24 Township 33, North, Range 9E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4" iron pipe with brass cap.
old BT

Resident witnesses:


1 1/4" Red Maple S8W 40'

Description of monument and accessories I established to perpetuate the original location of this corner.


New BT's

10" Spruce S70E 10' 10"
5" Red Maple S36E 15'
6" Red Maple S62W 10' 8"

FORM 985 R C MILLER CO. MILWAUKEE



○ = Corner monument restored.



Dated at Antigo, Wis., this 7th day of April, 1979.

Signature Raymond J. Hallisy Title Reg. Surveyor Registration No. 8-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy