State of Wisconsin

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. P - 7

History of original corner establishment:

CORNER RE-ESTABLISHED BY RHINELANDER PAPER CO.


Description of corner evidence found:

at...... o'clock..... M.

(Register of Deeds)

1/2" IRON BAR, FOUND IN PLACE.
FOUND 11/2" IRON PIPE WITH 3"
ALUMINUM CAP WITNESS
MONUMENT.

MARKED WITHESTREES



Description of monument and accessories	I established to perpetuate the original lo	cation of this corner.
BT'S PK NAIL SET IN CROSS	9" MAPLE 2" RON BAR, F.I.P. 2" RON BAR, F.I.P. 2" RON BAR, F.I.P.	C 1/4 5. 20 Cor 54 1K. West RIPCO
Dated at ELCHO	, Wis., this	Dec. , 19 81
Signature Mulliam & Kelly Title COUNTY SURVEYOR Registration No. 1098 (County Surveyor, Registered Land Surveyor, or other duly authorized official)		