## U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.


O = Corner monument restored.


LANGLADE COUNTY TOWN OF SUMMIT

N.W. SECTION CORNER - SEC 25

TOWN 33 N - R9E

HONUMENT 4" BRASS CAP





- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.
  - 1) CORNER SET IN 1930 COUNTY RESURVEY

    2 BEARING TREES
  - 2) CORNER RECOVEREDAND REMONUMENTED-7 APRIL 1979 ZORIGINAL B.TREES + Z NEW B. TREES
  - 3) 1 APRIL 1994 CORNER TIPPED AND BURIED FROM ROAD
    WORK. ORIGINAL ELM BT HOST (ROAD WORK). RESET ; DUG OUT
    CORNER. TREES BLAZED "B.T" ADDED COUNTY B.T PLAQUES
- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

  Describe witness monuments.

4 - BEARING TREES + COUNTY "BT" PLAGUES

(d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.


GLEARING

50. <u>E365</u> OF ROAD

279

- 1930'S

4. 1930'S




1) FIR-10"- 588°W-8.0' - 1979

2 RED MAPLE - 6" - N4E - 9' 11" - 1979

3 FIR-8.7" - 554°W - 14.0'- 1994

4 - BASSWOOD - 14"- SIZOW - 17" 1" - 1930'S ORIGINAL



K2/

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

N. A

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?

N. A.

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

N.A.

RAYMOND J. HALLISY

(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Laymond Libelling 4-

-11-94

Date

State of Wisconsin

SS.

ERTIFIED LAND CORNER RESTORATION	ION	ION	RESTORAT	CORNER	LAND	ERTIFIED	E
----------------------------------	-----	-----	----------	--------	------	----------	---

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

4" pine with brass cap

PT's

Elm

N/TOM

151

10 Basswood

S12W

17' 1"


Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

10" Balsam

Red Maple

91 11"



Wis., this 7th day of April 19 79. Dated at.....

Signature...

Ayunk f Halley Title Reg. Surveyor Registration No. S-685 (County Surveyor, Registration No. S-685)

(Register of Deeds)