

CERTIFIED LAND CORNER RESTORATION

Index No. V-20


State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:  
No evidence of any previous corner.

I Daniel K. Pleoger, do hereby  
certify that on the 1st day  
of March, 19 82, I ~~found~~ found est.  
~~evidence of~~ the E. 1/16  
corner of Sections 26 and 35  
Township 33, North, Range  
9 East, Fourth Principal Meridian,  
as described hereon; and that from this evidence  
I established a new monument and accessories  
as described hereon to perpetuate the original  
location of this corner.

Description of corner evidence found:  
Total distance from section corner 25-26-35-36 to 1/4 corner between sections  
26 and 35 is 2666.29 ft. at bearing N86-07-24W.  
Set E 1/16 1333.15 ft. intermediate.

Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2" iron pipe with brass cap stamped  
Monument projects 12" above ground.


T33N R9E

Marked NBTs:

- Maple 6" S43W 8.45 ft.
- Maple 5" N58E 30.60 ft.
- Scribed 1/16 - B.T.

E 1/16  $\frac{S | 26}{S | 35}$   
§1537 - 1982

FORM 985 W. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 22nd day of April, 1982

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within  
instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_  
at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

\_\_\_\_\_  
(Register of Deeds)

By \_\_\_\_\_ Deputy