Township 33					
as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.					
Resident witnesses:					
		······································			
T. 33N R. 9E.					
	1				
 	!	 - - 			
 	3P Q	 - 			
	i	i			
	!	- 			
1	i I	1			
	l 	1			
O = Corner monument restored.					

State of Wisconsin

I WILLIAM F. KELLY , do hereby certify that on the 2874 day of SEPTEMBER , 1977 , I found evidence of the CENTER SECTION corner of SECTION 30

County of LANGLADE

SS.


CERTIFIED LAND CORNER RESTORATION

Index No. T - 3

History of original corner establishment:

Description of corner evidence found:

LOCATED I.P. FROM O-I SURVEY



Description of monument SET CENTER SECTION SECTION SUBDIVISION ILLINOIS BASED ON EXISTING MONUMEN FROM ORIGINAL GOV MARKED NEW BLAZE	N BY OWENS - N LOCATION OF TS ESTABLISHED T'T SURVEY.	.SET	Ial location of this cor 2" x 42" IRON PII IITH BRASS CAP MAR	T33N R 9 9 - 28 - 7 - WFK
Dated at	(t)	28 7 day of		
Signature William	A S. Relly Title Rurveyor, Registered Land Survey	EGISTERED LAND S	VEVEYOR Registrati	
Office of Register of Deed instrument was filed in the at	s, County of is office for record on the M.	day o	, I hereby certif	y that the within , 19
((Register of Deeds)	······		
D.		Dooutu		