U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

	3 /, T. <u>33 N., R. 9</u> E., Langlade County, Wi
Corner was: (check all that apply)	
Restored through acceptance of an obliterated evidence Restored through acceptance of a found perpetuate	ence location.
□ Determined to be lost and re-established through a	proportionate methods.
(Show bearings and distances to PLSS corners us Restored/recovered/reestablished in a location that	sed for proportioning.) differs from a previously
established position. (Show difference in plan view	y below.) 3309310020
Check here if additional information is shown on the	
Describe record evidence, recovered physical evidence, or considered in the recovery/restoration of the corner.	ccupational evidence, testimonial evidence and all other evide
	G.E.H. G. C. L. L. L. L. CON MORNING AND
•	C. Fellows. Original bearing trees: birch, 20", N28°W, 10
	arker surveyed in 33-9 and described this corner: "This
•	showed us a birch stump which he said had been a bearing
	oad was graded. The road bends at the point he indicated. centerline two ft. north from its original position. We,
•	enterline of the road at the spot indicated by the bearing
•	ug with county backhoe at reading in road. At 37" down,
found 1" x 30" flanged bottom iron pipe. This pipe w	
accept it as the corner reset in 1936, and as the best ev	
	· · · · · · · · · · · · · · · · · · ·
Physical description of the monument set:	
Removed pipe found and replaced it with a 1 1/2" x 3	0" iron pipe with 4" brass cap bolted to top. Laid found
pipe alongside new monument set. Top of new monu	
monument at this time, as road will be patched in the	near future. no of the corner. Include a plan view drawing and indicate
decessories louridy set. Describe medsuring point on bed	of the corner. Include a plan view drawing and indicate aring trees. Show any topographic features that would
aid in future recovery of the corner.	
$\circ = 3/4$ " x 30" rebar with red plastic cap set flush with	n ground. Notes FB14-42
	700%
	<i>w</i>
1	
, ¥ 8" balsam	Ĩ
3# 20	-(b)
13.	
3/6	Ell 5 20 15 1
4-	5/4 COENER
SW COR 531	Found pipe SECON 531 (462'ORKINAL) & FOUND 4"IP
found stone " "	1762 URICINAL) INII 7 UNII 4 4 17
Sw cop 531 found stone C.T.H. "J"	470:
N 810 52 '38 W 2759.2'	(4)
N 810 52'38 W 2759.2'	N89°41'44'E 2459.78'
N 81°52'38 W 2759.2'	N89°41'44'E18 2459.78'
N 81°52'38 W 2759.2'	N89°41'44'E18 2459.78'
N 82°06'W 2759.2' (N 82°06'W 2758.75')	N89°41'44'E 2459.78'
N 81°52'38 W 2759.2'	N89°41'44'E18 2459.78'
N 82°06'W 2759.2' (N 82°06'W 2758.75') N/ /936 N/N N/N N/N N/N N/N N/N N/N N	N89°41'44'E 2459.78' N89°41'44'E 2459.78' y's & distances with Geodimeter total station The South 1/4
N 82°06'W 2758.75' N/N 19/08	N89°41'44'E 2459.78' N89°41'44'E 2459.78' y's & distances with Geodimeter total station The South 1/4
N82°06'W 2758.75' N/N 2759.2' (N82°06'W 2758.75') N/N N/N 9/08	N89°41'44'E 2459.78' N89°41'44'E 2459.78' y's & distances with Geodimeter total station
N82°06'W 2758.75' N/N 2759.2' (N82°06'W 2758.75') N/N N/N 99/08 3'± 0 3± 0 5'maple & G'maple	N89°41'44'E' 2459.78' N89°41'44'E' 2459.78' 3's & distances with Geodimeter total station The South 1/4 SURVEYORS SEAL corner of Section 3/ T. 33 N., R. 9 E.
N82°06'W 2758.75' N/ N/36 N/ N/36 N/ N/36 N/ N/36 N/ N/36 N/ N/ N/36 N	N89°41'44'E' 2459.78' N89°41'44'E' 2459.78' 3's & distances with Geodimeter total station The South 1/4 SURVEYORS SEAL corner of Section 3/ T. 33 N., R. 9 E.
N82°06'W 2758.75) . 2/ (N82°06'W 2758.75) . 2/ /936 5 maple 6 maple	N89°41'44'E' 2459.78' N89°41'44'E' 2459.78' 3's & distances with Geodimeter total station The South 1/4 SURVEYORS SEAL corner of Section 3/ T. 33 N., R. 9 E.
N 82°06' W 2758.75 N 87°06' W 2758.75 N 87°06' W 2758.75 N N N N N N N N N N N N N N N N N N	NB9°41'44'EN 2459.78' NB9°41'44'EN 2459.78' 3's distances with Geodimeter total station The South 1/4 SURVEYORS SEAL corner of Section 3/ T. 33 N., R. 9 E. Langlade County, WI
N82°06 W 2758.75 (N82°06 W 2758.75) // 936 Smaple Smaple Cluster David F. Tlusty, Langlade County Surveyor, certify that the corner location shown on this record was determined	NB9°41'44'EN 2459.78' X'S & distances With Geodimeter total station The South 1/4 SURVEYORS SEAL Corner of Section 3/ T. 33 N., R. 9 Langlade County, WI NDEX NO TLUSTY
N82°06 W 2759.2' (N82°06 W 2759.75) // 936 S maple C.T.H. J N82°06 W 2759.2' // 936 S maple Cluster	NB9°41'44'EN 2459.78' NB9°41'44'EN 2459.78' 3'S distances with Geodimeter total station The South 1/4 SURVEYORS SEAL corner of Section 3/ T. 33 N., R. 9 E. Langlade County, WI TLUSTY TLUSTY S.1390
N82°06 W 2759.2' (N82°06 W 2759.75) // 936 Simaple 6 maple cluster 1. David F. Thusty, Langlade County Surveyor, certify that the corner location shown on this record was determined by me or under my direction and control and that this	NB9°41'44'EN 2459.78' NB9°41'44'EN 2459.78' 3'S distances with Geodimeter total station The South 1/4 SURVEYORS SEAL corner of Section 3/ T. 33 N., R. 9 E. Langlade County, WI TLUSTY TLUSTY S.1390
N82°06 W 2759.2' (N82°06 W 2759.75) //936 Simaple 6 maple cluster 1. David F. Thusty Langlade County Surveyor, certify that the corner location shown on this record was determined by me or under my direction and control and that this	NB9°41'44'EN 2459.78' NB9°41'44'EN 2459.78' 3'S distances with Geodimeter total station The South 1/4 SURVEYORS SEAL corner of Section 3/ T. 33 N., R. 9 E. Langlade County, WI TLUSTY TLUSTY S.1390
N82°06 W 2759.2' (N82°06 W 2759.75) //936 Simaple 6 maple cluster 1. David F. Thusty Langlade County Surveyor, certify that the corner location shown on this record was determined by me or under my direction and control and that this	NB9°41'44'EN 2459.78' NB9°41'44'EN 2459.78' 3'S distances with Geodimeter total station The South 1/4 SURVEYORS SEAL corner of Section 3/ T. 33 N., R. 9 E. Langlade County, WI TLUSTY TLUSTY S.1390
N82°06 W 2759.2' (N82°06 W 2759.75) //936 Simaple 6 maple cluster 1. David F. Thusty, Langlade County Surveyor, certify that the corner location shown on this record was determined by me or under my direction and control and that this	NB9°41'44'EN 2459.78' X'S & distances With Geodimeter total station The South 1/4 SURVEYORS SEAL Corner of Section 3/ T. 33 N., R. 9 Langlade County, WI NDEX NO TLUSTY

WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of material. History: Cr. Register, February, 1987, No. 374, eff. 3-1-87.

A-E 7.08 U.S. public land survey monument record.

- (1) WHEN MONUMENT RECORD REQUIRED. A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and,
- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located, or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Department of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708.

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference ties to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees;
- (d) A plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed:
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished;
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through lost-cornerproportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr. Register, February, 1987. No. 374, eff. 3-1-87; am. (1) and (3) (c), Register, May, 1989, No. 401, eff. 6-1-89.