


CERTIFIED LAND CORNER RESTORATION

Index No. X-21

State of Wisconsin }  
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 25th day of February, 19 82, I found evidence of the Quarter corner of Sections 35 & 36 Township 33, North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witness



History of original corner establishment:

Original corner established by H.C. Fellows, Gov. deputy surveyor in 1860 from which hemlock 10" bears N75E 21 links and hemlock 10" bears N47W 12 links.


Description of corner evidence found:

Recovered an old 1" iron pipe with iron cap stamped: 1/4 S  
OBT unknown origin  
Black ash 10" N52W 30.15 ft. 35 | 36  
Scribed 1/4 S - B.T.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced 1" iron pipe with a 2 1/2" iron pipe with brass cap. T33N R9E  
Monument projects 12" above ground.  
Marked NBT: 1/4 35 | 36  
Maple 5" N1°W 21.0 ft.  
Black Ash 5" S68°E 12.16 ft.  
Black Ash 6" S10E 22.98 ft.  
Scribed 1/4 - B.T. S1537 = 1982

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 23 day of April, 1982

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy