


CERTIFIED LAND CORNER RESTORATION

Index No. W-21


State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 14th day of January, 19 81, I ~~found~~ rest. ~~corner of the~~ N 1/16 corner of Sections 35 & 36 Township 33, North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



FORM 965 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Corner established by unknown surveyor - destroyed by building of logging road.

Description of corner evidence found:

Corner re-established by retracement of previous survey of section 35. From old recovered NC 1/16 corner ran to recovered NE 1/16 corner for a distance of 1329.40 ft. at bearing S86-36-51E. Doubled distance and on line set N 1/16 corner between sections 35 and 36.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2" iron pipe with brass cap stamped: T33N R9E
Monument projects 12" above ground N 1/16 35 | 36
Marked NBTs S1537 - 1982
Maple 6" S35W 9.0 ft.
Maple 6" S62E 35.0 ft.
Scribed 1/16 - BT

Dated at Rhineland, Wis., this 22nd day of April, 1982

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy