## U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

The CS /16TH corner of Sec	tion <u>1</u> , T. <u>33</u> N., R. <u>10</u> E., Langlade County, W
Corner was: (check all that apply)  Restored through acceptance of an obliterat Restored through acceptance of a found per Determined to be lost and re-established the (Show bearings and distances to PLSS corner Restored/recovered/reestablished in a location established position. (Show difference in p	ed evidence location.  petuated location.  rough proportionate methods.  rners used for proportioning.)  on that differs from a previously
☐ Check here if additional information is shown	on the reverse side of this form. ence, occupational evidence, testimonial evidence and all other evider
1975 5/9 BILL KELLY - SET THE SC	VIGTH INTHE WRONG PLACE
2000 10/18 DEAN WILLIAMS FOUND B	•
I SET THE CS VIGTH AT MID-DIST	
THE SY4 TO THE CY4 OF WHICH THERE IS AN FENCE 660±, BEARIN	
3' OF THE TRUE 40 LINE, EAST OF	
•	
Physical description of the monument set:	•
I"x 30" BLACK I. P. AND 3 N.B.T.S. AND W.V.P 1.0' NORTH	
AND W. W. HO MORTH,	
	location of the corner. Include a plan view drawing and indicate on bearing trees. Show any topographic features that would
BEARINGS: MAGNETIC	20 SCALE 1" = 20' FOR BT.S.
DELIVINGS. HAGINE I'C	.4
	E'/4 NR5°52'56"E 1
	C'/4 N85°52'56"E 1-05
	N C 14
W'/4	C'/4 N85°52'56"E 1 05 2647.94'
	2647. 94'
1 3214.28' N.B.T. 5"OAK WINNICA	2647. 94'
1 3214.28' N.B.T. 5"OAK WINNICA	Z647. 94'  NOS STATE OF THE STA
3214.28' N.B.T. 5'OAK W/NAICA  N.B.T.  N.B.T.	Z647. 94'  NO SWAMP EDGE
N.B.T.  S"OAK W/NAIC 1870  N.B.T.  N.B.T.  8"BIRCH W/NAIL  8"BIRCH W/NAIL	Z647.94'  NO SWAMP EDGE  SET ("×30" 1.66LBS/FT, I.P.
N.B.T. 5"OAK W/NAICA N.B.T. 8"BIRCH W/NAIL 587°W 31.41'	Z647. 94'  NO SWAMP EDGE
32.14.28'  N.B.T.  S'OAK W/NAIL  N.B.T.  N.B.T.  N.B.T.  8'BIRCH W/NAIL  S87°W 31.41'  DEAD 12'ASPEN 20±'  DEAD 12'ASPEN 20±'	Z647. 94'  NO SWAMP EDGE  SET ("x30" 1.66LBS/FT, I.P.  CS /16TH
7 32.14.28'  N.B.T.  N	Z647. 94'  NO SWAMP EDGE  SET ("x30" 1.66LBS/FT, I.P.  CS 1/16 TH  FOUND BILL KELLYS  E
32.14.28'  N.B.T.  N.B	Z647. 94'  NO SET ("x30" 1.66LBS/FT, I.P.  CS 1/16 TH  FOUND BILL KELLY'S  CS 1/16 TH
32.14.28'  N.B.T.  N.B	Z647. 94'  NO SET ("x30" 1.66LBS/FT, I.P.  CS 1/16 TH  FOUND BILL KELLY'S  CS 1/16 TH
32.14.28'  N.B.T.  S'OAK W/NAIL  N.B.T.  N.B.T.  N.B.T.  SB7°W 31.41'  DEAD 12'ASPEN 20±'  STUB  WITHIN 1.0' OF COR.	Z647. 94'  NO SET ("x30" 1.66LBS/FT, I.P.  CS 1/16TH  FOUND BILL KELLYS  CS 1/16TH
32.14.28'  N.B.T.  N.B	Z647. 94'  NO SET ("x30" 1.66LBS/FT, I.P.  CS 1/16TH  FOUND BILL KELLYS  CS 1/16TH
32.14.28'  N.B.T.  N.B	SET I"X30" I.GGLBS/FT, I.P.  CS /16TH  SURVEYORS SEAL corner of Section 1
32.14.28'  N.B.T.  N.B	Z647. 94'  Z647. 94'  SET I"X30" I.66LBS/FT, I.P.  CS 1/16 TH  SURVEYORS SEAL  Corner of Section 1  T 33 N. P 10 F
32.14.28'  N.B.T.  N.B	SET ("x 30" 1.66LBS/FT, I.P.  CS 1/16TH  SURVEYORS SEAL  Corner of Section 1  T. 33 N., R. 10 E.  Langlade County, W
N.B.T.  S'OAK W/NAIL  N.B.T.  N.B.T.  N.B.T.  SB7°W 31.41'  DEAD 12 ASPEN 204'  STUB  WITHIN 1.0' OF COR.  N.B.T.  N.B	SET ("x30" 1.66LBS/FT, I.P.  CS 1/16 TH  SURVEYORS SEAL  Corner of Section 1  T. 33 N., R. 10 E.  Langlade County, W  NO  NO  NO  NO  NO  NO  NO  NO  NO  N
JEANA. WILLIAMS RLS-2468, certify that corner location shown on this record was determined.	SET ("x30" 1.66LBS/FT, I.P.  CS 1/16 TH  SURVEYORS SEAL  CORNER OF Section 1  T. 33 N., R. 10 E.  Langlade County, WI  The DEAN  WILLIAMS  The WILLIAMS  NO.
N.B.T.  8 BIRCH W/NAIL  S87°W 31.41'  DEAD 12 ASPEN 20±  STUB  WITHIN 1.0' OF COR.  N.B.T.  10 BIRCH W/NAIL  10 BIRCH W/NAIL  Corner location shown on this record was determ by me or under my direction and control and th U.S. Public Land Survey Monument Record is corn	SET ("*30" I.GLBS/FT, I.P.  CS /16 TH  SURVEYORS SEAL  CORNER TO E.  Langlade County, WI  The DEAN  WILLIAMS  The MILLIAMS  The SUBBRIT LAKE TO E.  SUBBRIT LAKE TO E.
N.B.T.  SBIRCH W/NALL  S87°W 31.41'  DEAD 12'ASPEN 20±  STUB  WITHIN 1.0' OF COR.  N.B.T.  10'BIRCH W/NALL  N.B.T.  10'BI	The CS //6TH  SURVEYORS SEAL  CORNER OF SECTION OF SECT
N.B.T.  8 BIRCH W/NAIL  S87°W 31.41'  DEAD 12 ASPEN 20±  STUB  WITHIN 1.0' OF COR.  N.B.T.  10 BIRCH W/NAIL  10 BIRCH W/NAIL  Corner location shown on this record was determ by me or under my direction and control and th U.S. Public Land Survey Monument Record is corn	The CS //6TH  SURVEYORS SEAL  CORNER OF SECTION OF SECT
N.B.T.  8 BIRCH W/NAIL  S87°W 31.41'  DEAD 12 ASPEN 20±  STUB  WITHIN 1.0' OF COR.  N.B.T.  10 BIRCH W/NAIL  10 BIRCH W/NAIL  Corner location shown on this record was determ by me or under my direction and control and th U.S. Public Land Survey Monument Record is corn	SET ("x30" 1.66LBS/FT, I.P.  CS '/16TH  SURVEYORS SEAL  Corner of Section 1  T. 33 N., R. 10  Langlade County, W  The WILLIAMS at this geometric belief.  SURMIT LAKE  SURMIT LAKE  SURMIT LAKE  SURMIT LAKE

## WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of material. History: Cr. Register, February, 1987, No. 374, eff. 3-1-87.

## A-E 7.08 U.S. public land survey monument record. (1) WHEN MONUMENT RECORD REQUIRED. A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and,

- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located, or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Department of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708.

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference ties to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees;
- (d) A plan view drawing depicting the relevant monuments and reference use which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed:
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished;
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through lost-corner-proportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr. Register, February, 1987, No. 374, eff. 3-1-87, am. (1) and (3) (c), Register, May, 1989, No. 401, eff. 6-1-89

State of Wisconsin County of $\angle ANGLADE$ ss.	IHis
I William F. Kelly , do hereby certify that on the 15T day of May , 19.75, I found evidence of the 5.18 corner of Sect.	
Township	De: Ca Fa
Resident witnesses:	
	Des
T. 33NR10E	N
	Da Sig Offi
	inst at
	•••••

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:



Index No. D-3

Description of corner evidence found:

Corner is located in a swamp. An old fence line that is down was found where corner is set.

escription of monument and accessories I established to perpetuate the original location of this corner. SHANBT 5" WHITE SPRUCE N SWAMP CORNER SET FROM CONTROL SURVEY. RAN CONTROL SURVEY BETWEEN THE SOUTH SECT . 1 T33N- R10E 1/4 COR. AND THE 5-1-75 ~11/2" B.I.P. WITH BRASS CAP Cedar Post painted Orange Next to Corner Pipe. NORTH 1/4 COR. SECT. WFK. T. 33N.-R.10E. BRASS CAP MARKED: SWAMP NBT 8" MAPLE
ELCHO, Wis., this /57 day of May, 1975 gnature William A. Kolley Title Registered Land Surveyor Registration No. 5 1098 (County Surveyor, Registered Land Surveyor, or other duly authorized official) ice of Register of Deeds, County of...., I hereby certify that the within o'clock M. (Register of Deeds)