

CERTIFIED LAND CORNER RESTORATION

Index No. J-3

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

ESTABLISHED ON 9-3-38 in Resurvey

I Raymond J. Hallisy, do hereby certify that on the 4th day of September, 1976, I found evidence of the 1/4 corner of Section 7 Township 33, North, Range 10 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:



4" IRON PIPE WITH BRASS CAP

Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW B.T.S
BASSWOOD 10" N44W 21 Foot 9 INCHS
HARD MAPLE 10" N27E 28 Foot 2 INCHS



○ = Corner monument restored.

Dated at Antigo, Wis., this 4th day of September, 1976.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE