

CERTIFIED LAND CORNER RESTORATION

Index No. 5-9

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 24th day of March, 1985, I found evidence of the Section corner of 8, 9, 16, 17 Township 33, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....
.....
.....

History of original corner establishment:

Corner Established in 1938 Resurvey

Description of corner evidence found:


4" Iron pipe with BRASS CAP



Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.S NO TREES NEAR for B.T.S
scribed wood post for B.T.S
10" post S56°E 9 FT } these posts set in 1938 Resurvey
10" post N39W 8.7 FT }

FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 24th day of March, 1985

Signature: Raymond J. Hallisy Title: Land Surveyor Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)
By _____ Deputy