

CERTIFIED LAND CORNER RESTORATION

Index No. J-13


State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 23rd day of March, 1985, I found evidence of the Section corner of 9, 10, 15, 16 Township 33, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

FORM 985 M. C. MILLER CO., MILWAUKEE




○ = Corner monument restored.

History of original corner establishment:

Established in 1938, Resurvey

Description of corner evidence found:

4" Iron pipe with BRASSCAP



Description of monument and accessories I established to perpetuate the original location of this corner.

New B.T.s

- Ash 7" S1E 4.0 FT
- Cedar 8" S68E 11.3 FT.
- Ash 4" N22E 18.9 FT
- Black Spruce 7" N20W 11.4 FT

Dated at Antigo, Wis., this 23rd day of March, 1985.

Signature Raymond J. Hallisy Title Land Surveyor Registration No. 3485
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By.....Deputy