

CERTIFIED LAND CORNER RESTORATION

Index No. 5-11

State of Wisconsin }
County of LANGLADE } ss.

I, RAYMOND S. HALLISY, do hereby certify that on the 24TH day of MARCH, 1985, I found evidence of the 4th corner of SECTION 9 & 16 Township 33, North, Range 10E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....
.....
.....

History of original corner establishment:

1930 RESURVEY

Description of corner evidence found:


4" IRON PIPE WITH BASS CAP



Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S

- 16" RED MAPLE N75W 2.8'
- 4" HARD MAPLE S67E 13.9'
- 14" RED MAPLE N74E 13.3'
- 14" RED MAPLE N47E 19.1'



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 24TH day of MARCH, 1985

Signature Raymond S. Hallisy Title LAND SURVEYOR Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By.....Deputy