U. S. PUBLIC LAND SURVEY MONUMENT RECORD


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following wine elements (a through i).

(a) identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

M.C. SET IN WATER 1938 COUNTY RESURVEY.



(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether as monument was found or placed.

WEAST SHORE OF KETTLE LAKE

'Z" MEANDER PIPE IS

5 18°E 23'9"

AT T33N RIOET 17 M.C. B-10-38 BELOW COR. 20LX5. ITEM D

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

B.T.S to BRASS CAP

0 4" RED MAPLE - NI3°E - 3'-4"

(2) 5" WHITE PINE - N72E - 12'8"

3 7" WHITE BIRCH - 538°E - 9.6"

0 6" RED OAK - 52°W- 3'

(1.) W.C to 4 CORNER Sec 11-14

* (2) W.B to M. C. - 4"BC.

3 M.C. - 1924 PLAT OF "LONG LAKE - WATER POWER LAKE" KETTE S 2 O TOREST ROAD

J 18.8

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or (2) a found perpetuated location?



(g&h) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

N.A.

5-0085

I. RAYMOND J. HALLISY

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Significant Hallisy

3/23/90 Date Affix Land Surveyor Seal

MAYMONE

HALLEY

ANTE