

CERTIFIED LAND CORNER RESTORATION

Index No. H-J 19

State of Wisconsin }
County of LANGLADE } ss.

I RAYMOND S. HALLIST, do hereby certify that on the 23RD day of MARCH, 1990, I found evidence of the MEANDER PIPE corner of _____ Township 33, North, Range 10 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

History of original corner establishment:

SET BY JAMES H. EDICK IN THE PLAT OF LONG LAKE-WATER POWER LAKE, AUGUST 6, 1924

Description of corner evidence found:

2" IRON PIPE WITH CAP, ON SOUTH SHORE OF WATER POWER LAKE, EAST OF THE OUTLET

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S
4" WHITE BIRCH S40E 5'7"
6" BALSAM S2W 7'6"
12" WHITE BIRCH S54W 10'7"
12" WHITE BIRCH S68W 10'10"

Dated at ANTIGO, Wis., this 23RD day of MARCH, 1990


Signature Raymond S. Hallist Title LAND SURVEYOR Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 W. E. MILLER CO., MILWAUKEE



○ = Corner monument restored.