

CERTIFIED LAND CORNER RESTORATION

Index No. G-H-21


State of Wisconsin }  
County of LANGLADE } ss.

History of original corner establishment:

I RAYMOND S. HALLISY, do hereby  
certify that on the 23<sup>RD</sup> day  
of MARCH, 1990, I found  
evidence of the MEANDER  
corner of.....  
Township 33, North, Range  
10 E, Fourth Principal Meridian,  
as described hereon; and that from this evidence  
I established a new monument and accessories  
as described hereon to perpetuate the original  
location of this corner.

Description of corner evidence found:

4" GALVANIZED PIPE  
ON NORTH SHORE OF  
GREATER BASS LAKE



Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S

10" WHITE BIRCH S40W 17' 8" (NOT SCRIBED)

6" RED OAK N29W 36' 6" (NOT SCRIBED)

NEW BO'S

NE CORNER OF COTTAGE N45W 72' 9"

SE CORNER OF COTTAGE S75W 61' 9"

Dated at ANTIGO, Wis., this 23<sup>RD</sup> day of MARCH, 1990


Signature Raymond S. Hallisy Title LAND SURVEYOR Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within  
instrument was filed in this office for record on the..... day of....., 19.....  
at..... o'clock..... M.

(Register of Deeds)

By..... Deputy

FORM 985 W & MILNER CO., MILWAUKEE



○ = Corner monument restored.