County of Langlade						
I. William E. Bandow do hereby certify that on the 10 th day of August 1976 I found evidence of the N. Hender Corner corner of Gov't Lot 3, Sec. 11 Township 33 North, Range 10 E Fourth Principal Meridian as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.						
Resident witnesses:						
Daniel Kuehl						
T33N RIOE						
1 1 1						
 						
1 1 1						
O = Corner monument restored.						

State of Wisconsin

CERTIFIED LAND CORNER RESTORATION

Index No. 6 -17 20

History of original corner establishment:

Description of corner evidence found:

Found meander corner on the south shore of Bass Lake. Corner is 2" capped iron pipe shown to me by Mr. Daniel Kuehl.

Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument in position and made new bearing trees.

BT's

12" Birch N 74-45'E 18.8'
10" Birch S 55-30'E 8.8'
5" Birch S 16-36'W 11.7'
9" Birch N 81-15'W 10.1'

Dated at Rhinelander	, Wis., this.	13 tn	day of	May	, 19 77
Signature Wallam E. Jane (County Surveyor, Regis	doz Title	Wisconsin	Land Surve	yor R	egistration No1182
, , , ,		-	-		w cortify that the within
Office of Register of Deeds, County of instrument was filed in this office for	record on the		day of	, 1 Herei	
at o'clock M.					
(Register of De	eds)				