

CERTIFIED LAND CORNER RESTORATION

33-10

Index No. J-24

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 10th day of May, 19 70, I found evidence of the E 1/16 corner of Section 13 Township 33, North, Range 10E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

J. Wein

J. Kryka

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake standing, marked 1/16 S12 S13

Description of monument and accessories I established to perpetuate the original location of this corner.


Set 2" pipe with brass cap, rock mound.

New B.T.'s


Yellow Birch 6" S28E 9 Ft. 11 inches

Red maple 4" S83 W 10 Ft. 9 inches

B.T.'s faced at base of tree and scribed BT.



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 10th day of May, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy