

CERTIFIED LAND CORNER RESTORATION


33-10

Index No. K-21

State of Wisconsin }
County of Lanlade } ss.

I Raymond J. Hallisy do hereby certify that on the 10th day of May, 19 70, I found evidence of the N 1/16 corner of Section 13 Township 33, North, Range 10E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:
J. Weiss
J. Krupa



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake standing in swamp, marked S14 S13 N1/16

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap.
New B.T.'s
10" Black Spruce N61E 17 Ft.
4" Tamarack S81W 4 Ft.
B.T.'s faced at base of tree and scribed BT.



Dated at Antigo, Wis., this 10th day of May, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE