

CERTIFIED LAND CORNER RESTORATION

33-10

Index No. K-19

State of Wisconsin }
County of Lan glade } ss.

History of original corner establishment:

I Raymond J. Hallisy, do hereby certify that on the 29 th day of August, 19 70, I found evidence of the North Center 1/16 corner of Section 14 Township 33 N, North, Range 10 E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Old squared stake standing with 1 inch iron pipe alongside.
This corner established in platting of Deepwoods Lake.

Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.


Set 2 inch iron pipe with brass cap 3 feet long.

New BT,S

10 inch White Birch N25E 14' 7"
12 Inch Red Pine N30W 25' 6"



FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 29 th day of August, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S 685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy