

CERTIFIED LAND CORNER RESTORATION

Index No. J-K 18


State of Wisconsin }
County of LANGLADE } ss.

I RAYMOND S. HALLISY, do hereby certify that on the 22ND day of MARCH, 1990, I found evidence of the MEANDER PIPE corner of 33 Township 1RE, North, Range 1RE, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

FORM 985 R. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

SET BY JAMES H. EDICK IN THE PLAT OF LONG LAKE - WATER POWER LAKE, AUGUST 6, 1924

Description of corner evidence found:

2" IRON PIPE ON WEST SHORE OF DEEPWOODS LAKE

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S

- 12" RED OAK S27W 2'6"
- 12" RED OAK N49W 8'1"
- 11" RED OAK N29W 5'1"
- 7" RED OAK N43E 3'7"

Dated at ANTIGO, Wis., this 22ND day of MARCH, 1990

Signature Raymond S. Hallisy Title LAND SURVEYOR Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy