

CERTIFIED LAND CORNER RESTORATION

Index No. N-7

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 4th day of Sept, 1976, I found evidence of the Y4 corner of Section 17 Township 33, North, Range 10 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....

History of original corner establishment:



ESTABLISHED OCTOBER 20, 1938
IN RESURVEY

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP
OLD B.T.S
Birch stump 16" S 18 W 30.6 LINKS
stone N 23 W 32.8 LINKS

Description of monument and accessories I established to perpetuate the original location of this corner.

Hard maple 10" S 64 E 24 Foot 7 inches
Hard maple 10" N 24 E 6 inches
Hard maple 5" S 44 W 2 Foot 1 inch



○ = Corner monument restored.

Dated at Ant 190, Wis., this 4th day of September, 1976

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By.....Deputy