County of LANGLADE

I established a new monument and accessories

as described hereon to perpetuate the original

location of this corner.

T. 33N R. 11E				
1				1
				l
			!	 -
			' 	-
		 	İ	! !
		· ·		I
١			<u> </u> -9_	
-		 	l	l
		 	! !	! }
	_ _	 	¦	-
١	1	· 		ı İ
	.	 		· ·

O = Corner monument restored.


CERTIFIED LAND CORNER RESTORATION

Index No. R - I

History of original corner establishment:

Description of corner evidence found:

4" GALVANIZED CAP IN A 4" IRON PIPE SET IN CONCRETE.
PATED 1930.



Description of monument and accessories established to perpetuate the original location of this corner.

ORRECTED RANGE No. ON CAP AND NARKED
WITNESS TREES. BLAZE TREES MARKED:

Sat N. CONCRETE.

CAP MARKED 2 524 519

Sat N. CONCRETE.

CAP MARKED 2 525 530

WE K. S1098

Jay of MARCH 1977.

Signature MULLAM S. Labe Title RESISTERED LAND SURVEYOR. Registration No. 51098

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of the marked in this office for record on the day of the marked in this office