æ

State of Wisconsin

O = Corner monument restored.


CERTIFIED	LAND	CODNED	DECTORA:	TION
CERHILL	LAND	CURINER	RESTURA	יוטוו

Index No. Q-1

History of original corner establishment:

Description of corner evidence found:

SET CORNER AT MID POINT BETWEEN 1/4 COR & SECT COR.



Description of monument and accessories I established to perpetuate the original location of this corner.

518 COR. SEC. 24 + 19 T 33 N R 10E - R 11E 6 - 28-79 W. F. K.	SIZ IRON PIPE WI BRASS CAP POWER POL	0 35,36	22. 20 E 0 5" A	ON PIPE	PK NAIL IN CROSS	
Dated at ELCHO	, Wis., this	28 da	ıy of	UNE	, 19.79	
Signature William &. (County Surveyor,	Title CO Registered Land Surveyor,	unty Sur	YEYOR orized official)	Registration 1	No. 5 - 1098	
Office of Register of Deeds, Counstrument was filed in this office	e for record on the		day of	l hereby certify th	at the within	
(Register	of Deeds)					