

CERTIFIED LAND CORNER RESTORATION

33-11

Index No. 0-1

State of Wisconsin }
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 29th day of May, 1968, I found evidence of the N 1/16 corner of Section 19 Township 33, North, Range 11, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:


Corner set in the 1930's By: E. F. Kowalke
C. W. Borth

Description of corner evidence found:
Found squared stake down at fence corner, rock mound.
Stake marked 1/8

Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

Set Std. 1 1/2" pipe with cap marked N 1/16 24 19. rock mound.



IP →
6" ASPEN N66°E 87'6"
SCRIBED BT

OR 26" WHITE PINE
S40°E 129'7"
SCRIBED BT

Dated at Antigo, Wis., this 29th day of May, 1968.

Signature: Raymond J. Hallisy Title: Reg. Land Surveyor Registration No. 8685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.

FORM 985 H. C. MILLER CO. MILWAUKEE