

CERTIFIED LAND CORNER RESTORATION

Index No. [REDACTED]

V-1

33-10

State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 26th day of March, 19 82, I found evidence of the Section corner of 25-36 - 30-31 Township 33, North, Range 9 & 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



History of original corner establishment:

Original corner established by H.C. Fellows, Gov. deputy surveyor in 1860 from which fir 10" bears S40W 44 links, white pine 10" N47W 36 links - spruce 8" N58E 6 links and elm 12" bears S10E 33 links.

Description of corner evidence found:

Recovered a 4" iron pipe filled with concrete and brass cap. Iron pipe is in good condition and securely set. Brass cap is not stamped.

OBT

Spruce stump 11" N48W 23.30 ft.
Scribed R9E S25

Description of monument and accessories I established to perpetuate the original location of this corner.

Stamped brass cap


Monument projects 6" above ground.

Marked NBTs:

Black ash 7" S83W 24.09 ft.
Black ash 6" N90W 17.95 ft.
Black ash 7" N68E 19.18 ft.
Scribed S.C. - B.T.

T33N
R9E 25|30 R10E
36|31
S1537 - 1982

FORM 985 W. E. MILLER CO. MILWAUKEE



○ = Corner monument restored.

Dated at Rhinelander, Wis., this 22nd day of April, 19 82.

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy