

CERTIFIED LAND CORNER RESTORATION

33-10  
Index No. U-22


State of Wisconsin }  
County of Lan glade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 22nd day of August, 1970, I found evidence of the M.C. corner of Section 25 Township 33, North, Range 10E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....  
.....  
.....

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Government Resurvey.

Description of corner evidence found:

Found old iron pipe

Description of monument and accessories I established to perpetuate the original location of this corner.

Set ~~XX~~ 2" pipe with brass cap in cement monument 4" by 2 Ft.

New B.T.'s

8" Red Pine N60E 7 Ft. 10 Inches  
8" White Birch S20W 19 Ft.

B.T.'S faced at base of tree and scribed BT



Dated at Angigo, Wis., this 22nd day of August, 1970

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....  
(Register of Deeds)

By.....Deputy